ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 12 | Shettihalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0088, W0049, W0045 | NA | Anjanya swamy temple road |
| **Segment No.** | **Total Length (m)** | |
| 12/C-W0088/S055514 | 50.36 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 50.36 | 77.525383 | 13.076932 | 77.525833 | 13.076819 | Anjanya swamy temple | Jayakumar house |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Emergency Reserve Fund (Desilting and Constructain of RCC Dran Veeranjaneya Badavane Abbigere village Near bus stop) in Ward 12 of Shetty halli sub div | 1000000 | 2015-16 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2015 - 2016 | Drain Maintenance | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | | 012-12-000090 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/112/2015-16 | 31/03/2016 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| | | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| KRIDL | | 999784.08 |
| **Phone No.** | **E-Mail ID** | |
| 9972045970 | | |

Ravi.N.K.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0088, W0049, W0045